

<Reference: 97125289H-FA Ltr2>

SRN: US-MF-000010993

March 2026

Urgent Medical Device Correction - Urgent Field Safety Notice ACCOLADE™ family of pacemakers & CRT-Ps

Dear Physician or Healthcare Professional (HCP),

You are receiving this letter to inform you that updated software, Brady software maintenance release 6 (SMR6), is now available for the ACCOLADE™ family of pacemakers and cardiac resynchronization therapy pacemakers (CRT-Ps)¹ which can address wandless ZIP telemetry (ZIP) disablements due to magnet detection during a battery impedance test. Our records indicate that you manage one or more devices that have experienced a magnet-induced false positive ZIP disablement and this communication provides important information for

- 1- Re-enabling ZIP telemetry in the pacemaker with Brady SMR6
- 2- Restoring remote monitoring via LATITUDE NXT Patient Management System by replacing the Communicator.

Summary

The Brady SMR5 update included a battery impedance test designed to detect elevated battery impedance and mitigate the risk of Safety Mode initiation. Under specific circumstances, the detection of a magnet during a daily battery impedance test may result in a false-positive detection of elevated battery impedance. This interaction may lead to unintended disablement of ZIP. If ZIP is disabled:

- In-person interrogation with a programmer will indicate that wandless ZIP telemetry is unavailable.
- The device will no longer communicate with the LATITUDE™ NXT Remote Patient Management System.

Importantly, magnet-induced false positive ZIP disablement does not reflect an actual high battery impedance condition and does not impact pacing therapy delivery.

Recommendations

- Upgrade LATITUDE™ Model 3300 programmers with Model 3869 v2.05 software (Brady SMR6).
- For each device in your clinic exhibiting a magnet-induced false positive, upgrade pacemaker software in-clinic by interrogating the device with a programmer upgraded with Brady SMR6 (Model 3869 v2.05) with an urgency commensurate with the desire to restore remote monitoring.
- After the device software is upgraded to Brady SMR6, provide the patient with a new replacement Communicator to restore remote monitoring.

Note the footer of the device follow-up report identifies the device firmware version; if the parenthetical at the end of the reported Firmware Version is “(3.24)” or greater, it has been updated with Brady SMR6.

- Update the medical record for each patient with an affected device by appending this letter to document resolution of this behavior.

Boston Scientific Technical Services can assist with evaluation of specific devices and coordination of Communicator replacement.

Additional Information

The Regulatory Authority of your country has been informed of this communication. Adverse events should be reported to Boston Scientific and Regulatory Authorities if appropriate. Our Product Performance Resource Center at www.bostonscientific.com/ppr, includes information on this topic and a device lookup tool. If you have additional questions, or would like to report on a clinical event, please contact your local representative or Technical Services.

A patient letter is available upon request, which can be distributed to the patient.

Alexandra Naughton

Vice President, Quality Assurance

¹The ACCOLADE family includes ACCOLADE, PROPONENT™, ESSENTIO™, and ALTRUA™ 2 SR-SL, DR-SL, and DR-EL pacemakers; and VISIONIST™ and VALITUDE™ CRT-Ps