

**Urgent!**  
**Field Safety Corrective Action (FSCA)**  
**Annex I: List of Affected Products**



Please note: This is no country specific list!

| Affected Products by FSCA-2017-10-16 |                                 |                               |         |            |
|--------------------------------------|---------------------------------|-------------------------------|---------|------------|
| #                                    | SAP article no.                 | Description                   | Lot no. | Serial no. |
| 1                                    | 70101.0892                      | HCU 20-600 Heater-Cooler Unit | N/A     | all        |
| 2                                    | 70101.0895                      | HCU 20-601 Heater-Cooler Unit | N/A     | all        |
| 3                                    | 70101.0896                      | HCU 20-602 Heater-Cooler Unit | N/A     | all        |
| 4                                    | 70102.8717<br>(old no.: 925771) | HCU 20-600 Base Unit          | N/A     | all        |
| 5                                    | 70101.7239                      | HCU 30-600 Heater Cooler Unit | N/A     | all        |
| 6                                    | 70102.2333<br>(old no.:965431)  | Heater Cooler Unit, EC        | N/A     | all        |
| 7                                    | 70102.2336<br>(old no.:965434)  | Heater Cooler Unit, AU        | N/A     | all        |
| 8                                    | 70102.8718<br>(old no.:939001)  | HCU 30 Base Unit 200-240 V    | N/A     | all        |
| 9                                    | 70103.4371<br>(old no.:704629)  | HCU 30 Base Unit 100-120 V    | N/A     | all        |
| 10                                   | 70103.4642<br>(old no.:704631)  | HCU 30 base unit 200 - 240 V  | N/A     | all        |
| 11                                   | 70103.4653<br>(old no.:705501)  | HCU 30 base unit Canadian/US  | N/A     | all        |