

	Immediate Action Required
	Action Required
✓	Information Only

# Urgent Field Safety Notice



<b>Product code and description:</b>	LK016.OPT - Optilite® Freelite® Kappa Free Kit LK016.M.OPT - Optilite® Freelite Mx™ kappa free kit LK016.10.OPT - Optilite® Freelite® Kappa Free Kit
<b>Reference:</b>	GLB135898
<b>Date:</b>	30 November 2020
<b>Issue:</b>	Positive bias affecting kit quality controls

## Summary of Issue:

Investigations at The Binding Site (TBS) have confirmed that the quality controls (QC), high and low controls, provided with the products and lot numbers indicated in the table below are consistently demonstrating a positive bias of approximately 15% compared to their assigned values. Customers may experience QC results consistently reporting results close to their upper acceptable limits, and QC failures may occur on affected lots.

The Binding Site has identified that the positive bias is limited to kit QC and sample results are not affected. When valid QC results are obtained in line with the product labelling the affected kits may continue to be used to report patient results.

## Details of affected devices:

Product	Lot number(s)/ software version	Expiry
LK016.OPT	432689	2021/11
LK016.M.OPT	437316	2021/11
LK016.10.OPT	433444	2021/11

## Advice on action to be taken by the user:

- Users may continue to use any remaining kits of the affected product in their stock. As per the product instructions for use sample results obtained should only be accepted if the control results are within  $\pm 20\%$  of the concentrations stated on the QC certificate provided.
- Please return your completed E-Back form TSWS18 (attached) to [Technical.support@bindingsite.com](mailto:Technical.support@bindingsite.com) or to your local Binding Site representative within one week of receiving this notification.



**Transmission of this Important information:**

- This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred.
- Please transfer this notice to other organisations on which this information has an impact.
- Please maintain awareness on this notice and resulting action for an appropriate period

Please contact your local Binding Site representative should you have additional questions on this matter.

Kind regards,



Colin Booth

Director of Regulatory and Quality

Should you require any further information please contact

Your local Binding Site Representative

or

Technical Support Group

UK: +44(0) 1214569696

[Technical.support@bindingsite.com](mailto:Technical.support@bindingsite.com)